


Driving Directions: Travel on state highway 120 North out of Cody and head west on highway 296 (Chief Joseph Highway) toward Sunlight Basin. Continue on 296 until you reach the turnoff for the Crandall Creek Ranger station (just before crossing Crandall Creek) on the left. Turn here and travel up to the trailhead. Park and hike across through property owned by the Crandall Creek Ranch (easement allows hiking) about one mile to the creek (do not take the left turn toward Lodge Pole Creek). The instream flow segment runs upstream from North Fork Crandall up to Hoodoo Creek.



Legend

-  WGFD Aquatic Regions
-  Access Roads
-  Other Roads
-  Perennial Stream
-  Instream Flow Filing
-  5th Level HUCs
-  Crandall Creek Watershed